Park Potomac Office Building "E"

Technical Assignment 1

Potomac, MD



Kyle Wagner

Structural Option (IP)

AE Consultant: Professor Kevin Parfitt

October 05, 2009

Structural Option

Potomac, MD

Consultant: Professor Parfitt

10/05/2009

Technical Assignment #1

Table of Contents

I.	Executive Summary	3
II.	Introduction	4
III.	Structural System Overview	4
	Foundation	4
	Superstructure	5
IV.	Codes and Design Standards	9
V.	Building Load Summary	11
	Gravity	11
	Wind	13
	Seismic	18
	Spot Checks	23
VI.	Appendices	27
	A: Wind	27
	B: Seismic	36
	C: Spot Check Calculations	46
	D: Photos	54

Structural Option Potomac, MD

Consultant: Professor Parfitt 10/05/2009

Technical Assignment #1

Executive Summary:

This report outlines the existing conditions of Park Potomac Office Building "E". This office building is a new addition to the recent community at Park Potomac in Potomac, MD. Office Building "E" is a seven story building with two large levels of below grade parking. Above grade, post tensioned concrete is prevalent, with beams and slabs spanning in each direction for all floors. This rigid building is designed using ordinary concrete moment frames to resist lateral forces in both directions, as well as to carry gravity loads.

Several different types of loadings were examined in this report. First, live loads, superimposed dead loads, and flat roof snow loads were calculated using ASCE 7-05. These loads were all found to be similar to the design loads used.

Wind loads were calculated for the building as well. Wind pressures, story forces and shears, and overturning moments were found in both directions due to wind loading. Wind forces in the East- West direction were found to control due to a larger surface area on the East and West building facades. Wind analysis revealed a base shear of 468K and an overturning moment of 30452 ft-k.

Seismic analysis by the structural engineer yielded a base shear of 300K in the design. The seismic analysis in this report was not as accurate due to some overly conservative assumptions made early in the seismic design. Differences in calculation of overall building weights may have also played a role in the discrepancies between the base shears.

Also included in this report is a spot check of a column and a floor slab from Office Building "E". A sixth floor column was first analyzed to determine the interaction diagram for axial and bending forces. The scope of this report required an analysis of the gravity loads only on the column. The column strength was more than adequate for the 690K axial load on the column. This additional strength will be important in the next phase, when lateral loads as well as axial loads are considered.

The spot checks on the building also included a spot check of the two way reinforced P1 Parking Level slab as well. These calculations showed very low moments on the bay selected, resulting from short 13' spans, as well as longer, thinner columns. This limited the required reinforcement from the analysis, which was reflected in the actual design.

Structural Option Potomac, MD

Consultant: Professor Parfitt 10/05/2009

Technical Assignment #1

Introduction:

Park Potomac Office Building "E" is located prominently off I-270 at Seven Locks and Montrose Roads. It is just one of several planned office buildings that are part of an "urban village" which mixes stunning town homes, Class A office space, and a wide range of amenities including dining and shopping.

Office Building "E" is a central part of the Park Potomac Master Plan. Its central location, at the end of Cadbury Avenue, makes it a focal point for this small community (Figure 1). It also puts it right at the main courtyard that will be a retail gathering point as well.



Figure 1: View from Cadbury Ave.

Structural System Overview

Foundations:

Park Potomac Office Building "E" consists of a seven story office building that sits above two levels of underground parking. The parking structure levels have a footprint of over 103,000 sq. ft. This is much larger than the office structure, which has a footprint of just more than 25,000 sq. ft.

This relationship has a large impact on the design of the foundation as well. The net allowable bearing pressures for the site are 4000 psi for undisturbed soil and 3,000 psi for foundations place on compacted structural fill. Over 150 spread footings are used throughout the project (Figure 2). All footings are 3000 psi concrete, and foundation walls are 4000 psi concrete. Spread footings, mostly ranging from $10' \times 10'$ to $12' \times 12'$, are used beneath the two levels of parking with no office building above. The majority of these footings are between 28'' and 34'' deep.

Consultant: Professor Parfitt 10/05/2009

Technical Assignment #1

Larger footings are used in the center of the project, taking load from the two parking levels and also from the office building above. These larger foundations are up to 52' x 64' in size and can be up to 62" deep.




Figure 2: Foundation Plan

Superstructure:

Floor system:

The slab on grade at the P2 Parking Level is a 5" thick, 3500 psi concrete slab. It is reinforced with 6x6 – W2.0 x W2.0 welded wire fabric. All other slabs contain 5000psi concrete. Two-way flat slabs are used at the P1 Parking level and the Plaza/First Floor Level as well. The slab is 8" thick at the P1 Level and 12" thick at the Plaza/First Floor Level. These slabs are reinforced as needed to resist negative moment at the columns and positive moments at midspan. Post tensioning is not used on the parking levels. Tying a post tensioned slab into foundation walls or other fixed structure does not allow the post tensioned slab to shrink when stressed. This would result in cracking of the slab if post tensioning was used below grade. Using this method for the parking garage

Structural Option Potomac, MD

Consultant: Professor Parfitt 10/05/2009

Technical Assignment #1

would also lead to difficulty in stressing the tendons as well. The designers of Office Building "E" use mild reinforcing below grade, and post tensioning for the slabs above grade.

Above the Plaza Level, Office Building "E" has seven levels of office floors. These floors are 7" thick post tensioned slabs. The post tensioning cables are 3.5" in diameter and induce forces in the slab ranging from 12.5 k/ft up to 35 k/ft. The post tensioning system uses banded tendons in the beams in the E-W direction, and a one way slab with uniform tendon layout in the N-S direction. This design allows for ease of construction when laying out the tendons. The post tensioned slab also allows for cantilevers that exist at the North and South ends of the structure. The load from a 12' cantilever on each end is taken by the uniformly spaced tendons that run through the slab.

Post tensioning is key to achieving several main goals on this project. The first main goal is that it allows for large spans in the floor layout. The design of this project requires that columns be placed around the exterior walls of the building and the interior core as well. This requires the beams and slab to span long distances over the floor. Post tensioning achieves these span requirements while maintaining a slab thickness of just 7 inches. Deflection over these spans is controlled effectively, while cracking is reduced as well.

Several steel shapes are utilized on the second floor slab to frame out the canopies above the East and West building entrances. This framing consists of TS5x2 shapes that are welded to ¾" plates and hung from the bottom of the slab by L4x4 angles. Steel shapes (W8x10) are also utilized as elevator rail supports throughout all floors.

Consultant: Professor Parfitt 10/05/2009

Technical Assignment #1

Gravity System:




Figure 3: Typical Framing Plan

The majority of the columns in the two levels of parking are 18" x 36" columns reinforced with 10 #9 bars. These columns are typically spaced between 15' and 30' apart. Columns supporting only the two parking levels consist of 4000 psi concrete, while 6000 psi concrete is utilized where load from the office building portion above is carried. Columns in the parking levels utilize drop panels to spread the load and resist punching shear.

In the office portion of the project, a relatively repetitive column layout is achieved. Excluding the central building core, 32 columns are used to transfer the load down through all seven levels. Long span post tensioned beams are used to transfer load from the floor to the columns. At typically 20" x 72" in size, these shallow, wide beams span in the E-W direction and continue the entire building width. In order to minimize the amount of columns in the tenant spaces and promote flexible space planning, large spans up to nearly 45' exist on each floor.

Structural Option Potomac, MD

Consultant: Professor Parfitt 10/05/2009

Technical Assignment #1

Columns on the office levels are 24" x 24" at every level and the concrete strength is varied throughout the levels to support an increased load as required. The plaza level through the fourth floor use 5000 psi concrete, while 4000 psi concrete is used above the fourth floor.

Lateral System:

Park Potomac Office Building "E" uses concrete moment frames to resist lateral forces. In the E-W direction, the wide post tensioned beams on each floor create a series of parallel frames that run up through all seven floors. These frames resist any lateral forces on the building in the parallel direction.

Similarly, forces in the N-S direction are resisted essentially by concrete moment frames as well. The concrete columns and the 7" slab, which is post tensioned in the N-S direction, combine to create a frame that resists later forces in this direction as well.

In both directions, the lateral forces are taken by the slab or beams and is transferred to the columns and down through the building.

Roof System:

The main roof system consists of a 7" to 8" structural slab. This slab varies in order to create the required roof slopes throughout. The roof contains a Penthouse/Mechanical space, as well as an elevator machine room. The penthouse roof is an 8" two way flat plate system, while the elevator machine room utilizes a 12" thick slab.

TS8x8 posts and TS 6x6 supports are used to frame a 16' tall screen-wall on the roof level to isolate the mechanical spaces from view.

Consultant: Professor Parfitt 10/05/2009

Technical Assignment #1

Codes & Design Standards:

Original Design:

- a. "The International Building Code 2003", International Code Council
- b. "Minimum Design Loads for Buildings and Other Structures" (ASCE7), American Society of Civil Engineers
- c. "Building Code Requirements for Structural Concrete, ACE 318-02", American Concrete Institute
- d. "ACI Manual of Concrete Practice- Parts 1 Through 5", American Concrete Institute
- e. "Manual of Standard Practice", Concrete Reinforcing Steel Institute
- f. "Post Tensioning Manual", Post Tensioning Institute
- g. "Manual of Steel Construction- Allowable Stress Design", Ninth Edition, 1989, American Institute of Steel Construction (Including specifications for structural steel buildings, specifications for structural joints using ASTM A325 of A490 bolts and AISC Code of Standard Practice)

Substituted for thesis analysis:

- a. "The International Building Code 2006", International Code Council
- b. "Minimum Design Loads for Buildings and Other Structures" (ASCE7), American Society of Civil Engineers
- c. "Building Code Requirements for Structural Concrete, ACI 318-08", American Concrete Institute

Structural Option Potomac, MD

Consultant: Professor Parfitt 10/05/2009

Technical Assignment #1

Material Strength Summary:

Concrete:

Footings 3000 psi
Foundation Walls 4000 psi
Columns Varies
Slab-on-Grade 3500 psi
Reinforced Slabs & Beams 5000 psi
Parking Structure 5000 psi
P.T. Concrete 5000 psi

Structural Steel:

Wide Flanges & Tees ASTM A992, Fy = 50 ksi

Square/Rectangular Hollow Shapes ASTM A500, Grade B, Fy = 46 ksi

Masonry:

Compressive Strength 1500 psi

Consultant: Professor Parfitt 10/05/2009

Technical Assignment #1

Gravity Loads:

Floor live loads were determined using ASCE 7-05. These loads were then compared to the design loads used in the original design. The design loads were largely the same as those from ASCE 7-05. A few of the loads used exceeded the required loadings from ASCE 7-05. These loads can be found below.

Table 1: Floor Live Loads						
Area	ASCE 7-05 Load (psf)					
Assembly Areas	100	100				
Corridors	100	100				
Corridors Above First Floor	80	80				
Lobbies	100	100				
Marquees & Canopies	75	75				
Mechanical Rooms	150	125				
Offices	80 + 20 psf Partitions	50				
Parking Garages	50	40				
Plaza, Top Floor Parking	Fire Truck Load or 250 psf	250				
Retail- First Floor	100	100				
Stairs and Exitways	100	100				
Storage (Light)	125	125				

The following superimposed dead loads were also considered in the design of the structure.

Table 2: Superimposed Dead Loads					
Area Design Load (psf)					
Floors 5					
Roof	10				

Structural Option Potomac, MD

Consultant: Professor Parfitt 10/05/2009

Technical Assignment #1

A flat roof snow load was calculated for this report as well. Beginning with a 30 psf ground snow load for Montgomery County, a flat roof snow load of 21 psf was calculated using the variables shown below from ASCE 7-05. This snow load of 21 psf was identical to the design snow load used by Cagley & Associates. Snow drift was not considered in this report, but will be analyzed more closely in future technical reports.

Table 3: Flat Roof Snow Load						
Ground Snow Load	P _g =	30	psf			
Snow Exposure Factor	C _e =	1.0				
(Terrain Category B)						
Thermal Factor	C _t =	1.0				
Importance Factor	l=	1.0				
Flat Roof Snow Load	p _f	21	psf			

Structural Option Potomac, MD

Consultant: Professor Parfitt 10/05/2009

Technical Assignment #1

Wind Loads:

Method 2, detailed in Chapter 6 of ASCE 7-05, was used to determine the wind loading for the building. Wind loadings in the N-S and the E-W directions were both analyzed. Detailed calculations can be found in Appendix A of this report. The analysis revealed the uniform pressures that occurred due to wind, which allowed the base shears and overturning moments to be determined as well.

In the E-W direction, the parking levels are completely below grade. The entrance is at the Plaza Level on the East and West sides of the building. This is reflected in the analysis. Roof uplift forces were not considered in this analysis. Results and loading diagrams can be found below.

	Table 4: East- West Design Pressures						
Level	Height (ft above Plaza)	Design Pressure Windward (psf)	Design Pressure Leeward (psf)	Total Pressure (psf)	Force of Total Pressure (k)	Story Shear Total (k)	Moment Windward (ft-k)
Plaza Level	0	6.83	-7.26	14.09	28.38	28.38	0
	9	6.83	-7.26	14.09			
2nd Floor	18	7.26	-7.26	14.52	49.54	77.92	892
	24.25	7.90	-7.26	15.16			
3rd Floor	30.5	8.44	-7.26	15.70	43.91	121.83	1339
	36.75	8.90	-7.26	16.16			
4th Floor	43	9.31	-7.26	16.57	46.34	168.17	1993
	49.25	9.67	-7.26	16.94			
5th Floor	55.5	10.01	-7.26	17.27	48.31	216.48	2681
	61.75	10.32	-7.26	17.58			
6th Floor	68	10.61	-7.26	17.87	49.98	266.46	3399
	74.25	10.88	-7.26	18.14			
7th Floor	80.5	11.13	-7.26	18.39	52.48	318.93	4224
	87	11.38	-7.26	18.64			
Main Roof	93.5	11.62	-7.26	18.88	27.46	346.39	2568
Penthouse	109.5	26.81	-7.26	34.07	121.98	468.38	13357
							30452

Base Shear	468	K
Overturning Moment	30452	ft-k

Consultant: Professor Parfitt 10/05/2009




Figure 4: East – West Design Pressures

Structural Option Potomac, MD

Consultant: Professor Parfitt 10/05/2009

Technical Assignment #1

Analysis results for the N-S wind direction can be found below. The parking level was not considered in this analysis because it was assumed that the wind would be totally blocked by the existing grade due to the site layout at these locations. Results and loading diagrams can be found below for the N-S wind direction.

	Table 5: North-South Design Pressures							
Level	Height (ft above Plaza)	Design Pressure Windward (psf)	Design Pressure Leeward (psf)	Total Pressure (psf)	Force of Total Pressure (k)	Story Shear Total (k)	Moment Windward (ft- k)	
Plaza Level	0	6.83	-5.08	11.92	13.67	13.67	0	
	9	6.83	-5.08	11.92				
2nd Floor	18	7.26	-5.08	12.34	23.99	37.67	432	
	24.25	7.90	-5.08	12.98				
3rd Floor	30.5	8.44	-5.08	13.52	21.55	59.21	657	
	36.75	8.90	-5.08	13.98				
4th Floor	43	9.31	-5.08	14.39	22.93	82.15	986	
	49.25	9.67	-5.08	14.76				
5th Floor	55.5	10.01	-5.08	15.09	24.06	106.20	1335	
	61.75	10.32	-5.08	15.40				
6th Floor	68	10.61	-5.08	15.69	25.01	131.21	1701	
	74.25	10.88	-5.08	15.96				
7th Floor	80.5	11.13	-5.08	16.22	26.36	157.57	2122	
	87	11.38	-5.08	16.47				
Main Roof	93.5	11.62	-5.08	16.70	13.84	171.42	1294	
Penthouse	109.5	26.81	-5.08	31.90	65.07	236.48	7125	
							15652	

Base Shear	236	K
Overturning		
Moment	15652	ft-k

Consultant: Professor Parfitt 10/05/2009

Technical Assignment #1




Figure 5: North - South Wind Pressures

Clearly, by analyzing the base shears and overturning moments in both directions, it is evident that the wind in the E-W direction is the most critical for the existing building. The base shear in this direction is 468 K, compared to only 236 in the N-S direction. The overturning moment reflects this relationship as well, with the E-W moment exceeding the other direction by nearly a factor of two.

This seems to make sense due to the larger surface area on the West and East faces of the building. These sides are about 225' in width, while the North and South faces are only around 125'. This is in line with the results obtained in this analysis.

The wind pressures obtained in this analysis result in forces that act at each story. These loads are transferred from the building façade by tributary area and act on the floors, which are considered rigid, and into the moment frames in both directions. These frames use columns, as well as the post tensioned beams and slab to resist lateral forces in both directions.

Park Potomac Office Building "E"

Structural Option Potomac, MD

Kyle Wagner

Consultant: Professor Parfitt 10/05/2009

Technical Assignment #1

The wind design variables that were available were consistent with the variables used in this analysis. The final design forces, however, were not available for direct comparison.

Consultant: Professor Parfitt 10/05/2009

Technical Assignment #1

Seismic Analysis:

The layout of the parking levels, and the surrounding ground, created unique seismic considerations for Office Building "E". The two levels of underground parking were mostly below grade, except on the North side of the structure. This scenario can be seen below.



Figure 6: View from North

In the figure, it is evident that on the North side, the structure is not braced by the ground. This is not the case for the other sides. Along the East and West, the parking is completely below grade and the parking is braced by the ground on each side.

In order to account for this exposure on the North side, and after consulting a member of the AE Faculty, a conservative assumption was made to deal with this problem. For the seismic analysis in this report, it was assumed that the parking levels were completely exposed for lateral loads in the N-S direction.

For loads in the E-W direction, the parking levels were almost completely below grade. For this direction, only the seven stories above grade were considered for analysis.

Consultant: Professor Parfitt 10/05/2009

Technical Assignment #1

The seismic analysis in this report was completed using Chapters 11 and 12 from ASCE 7-05. The equivalent lateral force procedure was determined to be valid for this analysis. Detailed calculations, including building self weights and other variables are available in Appendix B. The main variables used in the analysis are shown below.

Table 5: Seismic Design Variables						
			ASCE Reference			
Soil Classification		D	Table 20.3-1			
Occupancy		II	Table 1-1			
Importance Factor		1.0	Table 11.5-1			
Structural System		Ordinary Moment Frames	Table 12.2-1			
Spectral Response Acceleration, Short	S _s	0.156	USGS Website			
Spectral Response Acceleration, 1 s	S_1	0.051	USGS Website			
Site Coefficient	Fa	1.6	Table 11.4-1			
Site Coefficient	F_{v}	2.4	Table 11.4-2			
MCE Spectral Response Acceleration, Short	S_MS	0.2496	Eq. 11.4-1			
MCE Spectral Response Acceleration, 1 s	S _{M1}	0.1224	Eq. 11.4-2			
Design Spectral Acceleration, Short	S _{DS}	0.166	Eq. 11.4-3			
Design Spectral Acceleration, 1 s	S _{D1}	0.081	Eq. 11.4-4			
Seismic Design Category	S_{DC}	В	Table 11.6-2			
Response Modification Coefficient	R	3	Table 12.2-1			
Approximate Period Parameter	C_{t}	0.016	Table 12.8-2			
Building Height (E-W)	h _n	109.5'	-			
Building Height (N-S)	h _n	130.5'	-			
Approximate Period Parameter	Х	0.9	Table 12.8-2			
Approximate Fundamental Period (E-W)	Ta	1.095 s	Eq. 12.8-7			
Approximate Fundamental Period (N-S)	Ta	1.283 s	Eq. 12.8-7			
Long Period Transition Period	T_L	8.0 s	Fig. 22-15			
Seismic Response Coefficient (E-W)	Cs	0.0246	Eq. 12.8-2			
Seismic Response Coefficient (N-S)	Cs	0.021	Eq. 12.8-2			
Structure Period Exponent	k	1.0	Sec 12.8.3			

After calculation of the overall building self weight (See Appendix B), base shears can be calculated in order to calculate the forces on the structure. These base shears are shown below in Table 6. The large difference between the two directions is the fact that the

Structural Option Potomac, MD

Consultant: Professor Parfitt 10/05/2009

Technical Assignment #1

parking levels self weight was considered in the North-South analysis. This resulted in a vast difference in the building weights used for each case.

Table 6: Base Shears						
	Effective Seismic Seismic Response Base Sh Weight Coefficient (K)					
N-S	W = 61037 K	Cs = 0.0246	1502			
E-W	W = 27330 K	Cs = 0.0210	574			

After the calculation of the base shear values for each direction, the forces can be distributed throughout the building to determine forces at each level, story shear values, and overturning moments.

Table 7: Seismic Calculations									
Level	Story Weight (K)	N-S Height (ft)	E-W Height (ft)	N-S Forces (K) Fx	E-W Forces (K) Fx	N-S Story Shear Vx	E-W Story Shear Vx	N-S Moments (ft-k) Mx	E-W Moments (ft-k) Mx
Penthouse Roof	557	130.5	109.5	23	15	0	0	3063	1674
Main Roof	3858	114.5	93.5	289	153	23	15	33114	14337
7th Floor	3792	101.5	80.5	239	123	313	169	24231	9939
6th Floor	3777	89	68	198	99	551	292	17600	6711
5th Floor	3777	76.5	55.5	160	76	749	391	12254	4209
4th Floor	3777	64	43	125	54	909	467	7998	2342
3rd Floor	3777	51.5	30.5	92	35	1034	521	4756	1064
2nd Floor	3840	39	18	64	18	1127	556	2502	324
Plaza/First Floor	19043	21	0	252	0	1191	574	5287	0
P1 Level*	14085	10	-	59	-	1443	-	589	-
P2 Level/Foundation*	751	0	-	0	-	1502	-	0	-
Total:	61037	130.5	109.5	1502	574			111395	40600

Consultant: Professor Parfitt 10/05/2009




Figure 7: East- West Seismic Forces

Consultant: Professor Parfitt 10/05/2009

Technical Assignment #1




Figure 8: North- South Seismic Forces

The seismic analysis competed by the structural engineer yielded a base shear of only 300K. This is a large difference from the values obtained in this analysis. This is especially true in the N-S direction, which yielded a base shear of just over 1500 K. The conservative assumption used to deal with the site layout appears to have been overly conservative. This is clear when analyzing the building weights used in both directions. The inclusion of the parking structure in the building weight for the analysis in the N-S direction added almost 34000 Kips to the total weight. This is enormous, especially considering that the building weight for the E-W analysis was 27330 K total. This extreme addition was mostly due to the parking level slabs, which covered around 110,000 sq. ft. a piece, and were up to 12" thick.

It is likely that other discrepancies between the calculations were due to the calculation of the building self weight. All variables found were consistent with those used by the structural engineer; however, the building self weights used by the structural engineer were not available for confirmation. It is likely that this is where the differences existed. It is clear that less conservative assumptions were made by the structural engineer, which led to much lower base shears, as well as story forces and moments.

Consultant: Professor Parfitt 10/05/2009

Technical Assignment #1

Spot Checks:

Column at H-2:

The first spot check completed for this report was a check of the sixth floor column in the office building portion of the building. This column was at gridlines H-2. The tributary area was 1008 sq. ft. and can be seen on Figure 9 below.




Figure 9: Column at H-2 Grid

Several calculations were performed on this column to determine it capacity for axial as well as bending forces. These calculations are available in Appendix C. After calculating M_n and P_n at numerous loadings, an interaction diagram was drawn for the column. These forces and the interaction diagram are below.

Table 8: Column Spot Check					
Mn (ft-k)	Pn (k)				
0	-379.2				
351.7	0				
701	736.7				
408.8	1957.5				
0	2316.1				

Consultant: Professor Parfitt 10/05/2009

Technical Assignment #1




Figure 10: Column Interaction Diagram

Considering axial forces only, the column is more than adequate for the 690K required from it. This is also clear from looking at the interaction diagram as well. This report does not take into account the bending forces on the column.

In reality, the lateral loads on the building will induce moment in each of the columns. As these columns resist moment, they are stressed further towards their failure point. This interaction diagram will be analyzed further as the moments are calculated from the lateral loads in further reports.

Consultant: Professor Parfitt 10/05/2009

Technical Assignment #1

Two-Way Slab:

The P1 Level slab was also analyzed in this report as well. A 13' \times 28' bay, between gridlines 7P-8P and FP-GP was examined to check the reinforcing in the slab. This section of the 8" thick slab was an interior bay supported by 18" \times 36" columns. It is seen below in Figure 10.




Figure 10: P1 Level Slab Portion

In the analysis, a slab dead load of 100 psf and a garage live load of 40 psf were used, which yielded a 200 psf ultimate load. Upon checking the slab thickness with ACI 318 deflection control limits (Table 9.5c) I found that the slab thickness did not comply with these requirements. Therefore, deflections calculations would have to be done on this slab to ensure that the deflection was adequate.

Also, upon calculation and distribution of moments along the frames in this analysis, it was found that the moments were extremely small in the vertical direction. This is due mainly to the 13' span distance, as well as the columns being in a longer orientation in the vertical direction. This yielded small amounts of reinforcement in that direction, which is consistent with the design of the slab.

More detailed calculations can be found in Appendix C.

No spot checks were performed on the post tensioned slabs or beams due to the fact that a gravity only analysis of these members would yield insignificant results due to the

Park Potomac Office Building "E"

Structural Option Potomac, MD

Kyle Wagner

Consultant: Professor Parfitt 10/05/2009

Technical Assignment #1

fact that these post tensioned members are largely responsible for resisting lateral forces. These members will be examined more closely in the next technical reports as the lateral loads on the structure are more closely considered.

Park Potomac O	ffice Building	"E"
----------------	----------------	-----

Structural Option Potomac, MD

Consultant: Professor Parfitt 10/05/2009

Technical Assignment #1

Appendix A: Wind

Structural Option Potomac, MD

Consultant: Professor Parfitt 10/05/2009

	KYLE WAGNER WIND ANALYSIS TECH !	1
	WIND IN EAST-WEST DIRECTION	
	DETERMINE VELOCITY PRESSURES, 92 9h	
	BASIC WIND SPEED	
	POTOMAC, MD V= 90 mph [FIGE-1]	
	WIND DIRECTIONALITY FACTOR	
	Kd = 0.85 [TABLE 6-4]	
	IMPORTANCE FACTOR	
	I = 1.0	
	EXPOSURE CATEGORY: B	
	TOPOGRAPHIC FACTOR	
	Ket = 1.0	
*	DETERMINE VEL PRESSURE EXPOSORE COEFF KE, KA	
	SEE FIGURE FOR DATA	
	DETERMINE VEL PRESSURES	
	92 = 6.00256K2K2ELKdV2I	
	9h = 0.00256 Kh Kzt KdN2 I	
	SEE FIGURE FOR DATA	
	GUST EFFECT FACTORS	
	ASSOME: MOST LIKELY RIGID	
	7, = 100/H = 100/93.5 = 1.07 71 1. RIGID	
	G=0.85 (6.5.8.1)	

Structural Option Potomac, MD

Consultant: Professor Parfitt 10/05/2009

KYLE WAGHER	WIND ANALYSIS	TECH 1	2
	LENCLOSED W/PO	ARAPET (161)	
Pr 9p	GC, GURE FOR DATA T LOW RISE , RIG		
DETERMIN	E 92 194 CP GCP		
WILLOWAR	Design Wind Presso D: $P_z = q_z GC_p - q_z$ D: $P_i = q_i GC_p - q_z$	In (GCpi)	
see fi		h	

Consultant: Professor Parfitt 10/05/2009

Table 9: E-W Basic Wind Analysis Factors						
Exposure B						
Case 2						
L (Most conservative) =	127.5	ft				
B=	223.75	ft				
L/B=	0.570					
Basic Wind Speed	V=	90				
Wind Directionality Factor	K _d =	0.85				
Importance Factor	I=	1.0				
Exposure Category	Category	В				
Topographical Factor	K _{zt} =	1.0				
Gust Effect Factor	G=	0.85				
Cp Windward	C _p =	0.8				
Cp Leeward	C _p =	-0.5				
G _{cpi} Windward		0.18				
G _{cpi} Leeward		-0.18				
GC _{pn} Windward		1.5				
GC _{pn} Leeward		-1				

Table 10: E-W Velocity Pressure Exposure Coefficients, Kh and Kz								
Level	Height (ft above Plaza)	Kz, Kh, Kp	qz, qh, qp Windward	qz, qh Leeward				
Plaza Level	0	0.570	10.047	17.087				
	9	0.570	10.047	17.087				
2nd Floor	18	0.605	10.671	17.087				
	24.25	0.659	11.620	17.087				
3rd Floor	30.5	0.704	12.407	17.087				
	36.75	0.742	13.085	17.087				
4th Floor	43	0.776	13.686	17.087				
	49.25	0.807	14.227	17.087				
5th Floor	55.5	0.835	14.721	17.087				
	61.75	0.861	15.177	17.087				
6th Floor	68	0.885	15.601	17.087				
	74.25	0.908	15.998	17.087				
7th Floor	80.5	0.929	16.371	17.087				
	87	0.950	16.739	17.087				
Main Roof	93.5	0.969	17.087	17.087				
Penthouse Level	109.5	1.014	17.876	17.087				

Structural Option Potomac, MD

Consultant: Professor Parfitt 10/05/2009

Table 11: E-W Calculation of Design Wind Pressures									
					Wind	lward	Leev	ward	
	Height	External	External		Net	Net	Net	Net	
	(ft	Pressure	Pressure	Internal	Pressure	Pressure	Pressure	Pressure	
	above	Windward	Leeward	Pressure	P Pos	P Neg	P Pos	P Neg	
Level	Plaza)	(psf)							
Plaza									
Level	0	6.83	-7.26	3.22	3.61	10.05	-10.48	-4.04	
	9	6.83	-7.26	3.22	3.61	10.05	-10.48	-4.04	
2nd Floor	18	7.26	-7.26	3.22	4.04	10.47	-10.48	-4.04	
	24.25	7.90	-7.26	3.22	4.68	11.12	-10.48	-4.04	
3rd Floor	30.5	8.44	-7.26	3.22	5.22	11.65	-10.48	-4.04	
	36.75	8.90	-7.26	3.22	5.68	12.12	-10.48	-4.04	
4th Floor	43	9.31	-7.26	3.22	6.09	12.52	-10.48	-4.04	
	49.25	9.67	-7.26	3.22	6.46	12.89	-10.48	-4.04	
5th Floor	55.5	10.01	-7.26	3.22	6.79	13.23	-10.48	-4.04	
	61.75	10.32	-7.26	3.22	7.10	13.54	-10.48	-4.04	
6th Floor	68	10.61	-7.26	3.22	7.39	13.83	-10.48	-4.04	
	74.25	10.88	-7.26	3.22	7.66	14.10	-10.48	-4.04	
7th Floor	80.5	11.13	-7.26	3.22	7.91	14.35	-10.48	-4.04	
	87	11.38	-7.26	3.22	8.16	14.60	-10.48	-4.04	
Main Roof	93.5	11.62	-7.26	3.22	8.40	14.84	-10.48	-4.04	

Structural Option Potomac, MD

Consultant: Professor Parfitt 10/05/2009

Technical Assignment #1

Table 12: E-W Design Pressures								
Level	Height (ft above Plaza)	Design Pressure Windward (psf)	Design Pressure Leeward (psf)	Total Pressure (psf)	Force of Total Pressure (k)	Story Shear Total (k)	Moment Windward (ft-k)	
Plaza Level	0	6.83	-7.26	14.09	28.38	28.38	0	
	9	6.83	-7.26	14.09				
2nd Floor	18	7.26	-7.26	14.52	49.54	77.92	892	
	24.25	7.90	-7.26	15.16				
3rd Floor	30.5	8.44	-7.26	15.70	43.91	121.83	1339	
	36.75	8.90	-7.26	16.16				
4th Floor	43	9.31	-7.26	16.57	46.34	168.17	1993	
	49.25	9.67	-7.26	16.94				
5th Floor	55.5	10.01	-7.26	17.27	48.31	216.48	2681	
	61.75	10.32	-7.26	17.58				
6th Floor	68	10.61	-7.26	17.87	49.98	266.46	3399	
	74.25	10.88	-7.26	18.14				
7th Floor	80.5	11.13	-7.26	18.39	52.48	318.93	4224	
	87	11.38	-7.26	18.64				
Main Roof	93.5	11.62	-7.26	18.88	27.46	346.39	2568	
Penthouse	109.5	26.81	-7.26	34.07	121.98	468.38	13357	
							30452	

East- West Direction

Base Shear	468.38	K
Overturning		
Moment	30452	ft-k

Structural Option Potomac, MD

Consultant: Professor Parfitt 10/05/2009

Table 13: N-S Basic Wind Analysis Factors						
Exposure B						
Case 2						
L (Most Conservative)=	223.75	ft				
B=	127.5	ft				
L/B=	1.754901961					
Basic Wind Speed	V=	90				
Wind Directionality Factor	K _d =	0.85				
Importance Factor	I=	1				
Exposure Category	Category	В				
Topographical Factor	K _{zt} =	1				
Gust Effect Factor	G=	0.85				
Cp Windward	C _p =	0.8				
Cp Leeward	C _p =	-0.35				
G _{cpi} Windward		0.18				
G _{cpi} Leeward		-0.18				
GC _{pn} Windward		1.5				
GC _{pn} Leeward		-1				

Table 14: N-S Velocity Pressure Exposure Coefficients, Kh and Kz								
Level	Height (ft above Plaza)	Kz, Kh, Kp	qz, qh, qp Windward	qz, qh Leeward				
Plaza Level	0	0.570	10.047	17.087				
	9	0.570	10.047	17.087				
2nd Floor	18	0.605	10.671	17.087				
	24.25	0.659	11.620	17.087				
3rd Floor	30.5	0.704	12.407	17.087				
	36.75	0.742	13.085	17.087				
4th Floor	43	0.776	13.686	17.087				
	49.25	0.807	14.227	17.087				
5th Floor	55.5	0.835	14.721	17.087				
	61.75	0.861	15.177	17.087				
6th Floor	68	0.885	15.601	17.087				
	74.25	0.908	15.998	17.087				
7th Floor	80.5	0.929	16.371	17.087				
	87	0.950	16.739	17.087				
Main Roof	93.5	0.969	17.087	17.087				
Penthouse Level	109.5	1.014	17.876	17.087				

Structural Option Potomac, MD

Consultant: Professor Parfitt 10/05/2009

	Table 15: N-S Calculation of Design Wind Pressures									
					Wind	ward	Leev	ward		
	Height	External	External		Net	Net	Net	Net		
	(ft	Pressure	Pressure	Internal	Pressure	Pressure	Pressure	Pressure		
	above	Windward	Leeward	Pressure	P Pos	P Neg	P Pos	P Neg		
Level	Plaza)	(psf)								
Plaza Level	0	6.83	-5.08	3.22	3.61	10.05	-8.30	-1.87		
	9	6.83	-5.08	3.22	3.61	10.05	-8.30	-1.87		
2nd Floor	18	7.26	-5.08	3.22	4.04	10.47	-8.30	-1.87		
	24.25	7.90	-5.08	3.22	4.68	11.12	-8.30	-1.87		
3rd Floor	30.5	8.44	-5.08	3.22	5.22	11.65	-8.30	-1.87		
	36.75	8.90	-5.08	3.22	5.68	12.12	-8.30	-1.87		
4th Floor	43	9.31	-5.08	3.22	6.09	12.52	-8.30	-1.87		
	49.25	9.67	-5.08	3.22	6.46	12.89	-8.30	-1.87		
5th Floor	55.5	10.01	-5.08	3.22	6.79	13.23	-8.30	-1.87		
	61.75	10.32	-5.08	3.22	7.10	13.54	-8.30	-1.87		
6th Floor	68	10.61	-5.08	3.22	7.39	13.83	-8.30	-1.87		
	74.25	10.88	-5.08	3.22	7.66	14.10	-8.30	-1.87		
7th Floor	80.5	11.13	-5.08	3.22	7.92	14.35	-8.30	-1.87		
	87	11.38	-5.08	3.22	8.17	14.60	-8.30	-1.87		
Main Roof	93.5	11.62	-5.08	3.22	8.40	14.84	-8.30	-1.87		

Park Potomac Office Building "E"

Kyle Wagner

Structural Option Potomac, MD

Consultant: Professor Parfitt 10/05/2009

Technical Assignment #1

Table 16: N-S Design Pressures								
Level	Height (ft above Plaza)	Design Pressure Windward (psf)	Design Pressure Leeward (psf)	Total Pressure (psf)	Force of Total Pressure (k)	Story Shear Total (k)	Moment Windward (ft-k)	
Plaza Level	0	6.83	-5.08	11.92	13.67	13.67	0	
	9	6.83	-5.08	11.92				
2nd Floor	18	7.26	-5.08	12.34	23.99	37.67	432	
	24.25	7.90	-5.08	12.98				
3rd Floor	30.5	8.44	-5.08	13.52	21.55	59.21	657	
	36.75	8.90	-5.08	13.98				
4th Floor	43	9.31	-5.08	14.39	22.93	82.15	986	
	49.25	9.67	-5.08	14.76				
5th Floor	55.5	10.01	-5.08	15.09	24.06	106.20	1335	
	61.75	10.32	-5.08	15.40				
6th Floor	68	10.61	-5.08	15.69	25.01	131.21	1701	
	74.25	10.88	-5.08	15.96				
7th Floor	80.5	11.13	-5.08	16.22	26.36	157.57	2122	
	87	11.38	-5.08	16.47				
Main Roof	93.5	11.62	-5.08	16.70	13.84	171.42	1294	
Penthouse	109.5	26.81	-5.08	31.90	65.07	236.48	7125	
							15652	

North- South Direction

Base Shear	236.48	K
Overturning Moment	15652	ft-k

Structural Option Potomac, MD

Consultant: Professor Parfitt 10/05/2009

Technical Assignment #1

Appendix B: Seismic

Consultant: Professor Parfitt 10/05/2009

KYLE WAGNER TECH I SEISMIC 10/01/09 1
NOT DETACHED FOR 2 FAMILY DWELLINGS NOT ON AG STORAGE NO SPECIAL CONSIDERATIONS
SEISMIC GROUND MOTION VALUES
DETERMINE SS AND S, [FIG 22-1 AND 22-14]
5,= 0.156
5,=0,051
S5 > 0.15 AND S, >0.04
DETERMINE SOIL SITE CLASS
SOIL SITE CLASS D
DETERMINE SMS AND SMI
Sms = FaSs = 1.6 (0.156) = 0.2496
Sm, = FyS, = 2.4 (0.051) = 0.1224
DETERMINE SOS AND SOI
Sps = 2 Sms/3 = 2(0.2496)/3 = 0.166
Sp1 = 2 Sm1 /3 = 2 (0.1224)/3 = 0.081
SEISMIC DESIGN CATEGORY
5, =0.156 70.15 AND 5, =0.051 70.04
DETERMINE OCCUPANCY CATEGORY IBC TABLE 1604.5 (II)
I, I OR II YES
5, 46.75
SIMPLIFIED DESIGN? - No > 3 STORIES
FIND SDC:
So1 = 6.081 0.067 & So1 & 6.133 SEISMIC DESIGN CAT B

Consultant: Professor Parfitt 10/05/2009

KYLE WAGNER TECH! SEISMIK 10/01/09	2
PERMITTED ANALYTICAL PROCEDURES	
SDC B	
· Use · EQUIVALENT LATERAL FORCE PROCES · MODAL RESPONSE SPECTRUM ANAL · SEISMIC RESPONSE HISTORY PROCED	4515
USE ELFP	
DETERMINE RESPONSE MODIFICATION CORFE R	
ORDINARY MOMENT FRAMES - R=3	
IMPORTANCE FACTOR I = 1.0	
DETERMINE APPROXIMATE FUNDAMENTAL PERIOD	
$T_{\alpha} = C_{\pm}h_{n}^{X}$	
· FOR E-W FORCE · FOR N-3 FORCE	
$h_n = 109.5$ $h_n = 130.5$ TO PENTHOUSE ROOF TO PENTHOUSE	EOOF
FOR CONC. MOMENT RESISTING FRAMES CE = 0.011	- X = 0-9
Ta = Cihn = 0.016 (109.51)0.9 Ta = 0.016 (130.5))0.9
Ta=1.695 s Ta=1.283 s	
TL=87Ta	
$C_S = \frac{S_{D1}}{T(\frac{R}{2})} \leq \frac{S_{DS}}{(\frac{R}{2})}$ $C_S = \frac{0.081}{1.283(3)} = 0.0210 \leq 0$	3=6.055/
C5 = 0.081 = 0.0246 4 0.166 = 0.055/	,
Cs = 0.0246 Cg=0.0210	*
S1=0.051 40.6 KEW = 1.2975 KN-6=1.3915 B	LETEROLATED L
PLEASE SEE FIGURES FOR BUILDING WEIGH AND FORCE CALCULATIONS	75

Structural Option Potomac, MD

Consultant: Professor Parfitt 10/05/2009

Table 17: Basic Building Information						
Level	Height Above Plaza (in)	Floor-Floor Distance (ft)	Area (SF)	Slab Thickness (in)		
Penthouse Roof	109.5	16	2000	8		
Main Roof	93.5	13	26350	7		
7th Floor	80.5	12.5	26350	7		
6th Floor	68	12.5	26276	7		
5th Floor	55.5	12.5	26276	7		
4th Floor	43	12.5	26276	7		
3rd Floor	30.5	12.5	26276	7		
2nd Floor	18	18	26276	7		
Plaza/First Floor	0	11	108989	12		
P1 Level*	-11	10	108989	8		
P2 Level/Foundation*	-21	0	103561	5		
* Parking Ramp Excluded						

Table 18: Penthouse Level Self Weight					
(Assu	me Elevator Room at 16': (Conservativ	e)		
Slabs:	Penthouse		200	K	
	Elevator Machine Room		95	K	
Superimposed Dead	10 psf		263	K	
Penthouse Total:			557	К	

Consultant: Professor Parfitt 10/05/2009

Table 19: Roof Self Weight				
Slabs:	Main Roof Slab		2306	K
PT Beam Weight:			879	K
Primary Column Weight:	(32) 24" x 24" Columns		125	K
Superimposed Dead:	10 psf		264	K
Building Core:				
	(12) 12x24 Columns		23	K
	Core Beams (12" x 30")		17	K
	Core Beams (12" x 24")		24	K
	Core Beams (12" x 20")		22	K
Building Envelope:				
	15 psf Assumed		62	K
Mechanical:				
	AHU (2 units)		127	K
	Cooling Tower		6	K
	AC Unit		4	K
Roof Total:			3858	K

	Table 20: Level 7 Self Weight					
Slab Weight:	7" Thick Slab		2306	K		
PT Beam Weight:			879	K		
Primary Column Weight:	(32) 24" x 24" Columns		245	K		
Superimposed Dead:	5 psf		131	K		
Building Core:						
	(12) 12" x 24" Columns		46	K		
	Core Beams (12" x 30")		17	K		
	Core Beams (12" x 24")		24	K		
	Core Beams (12" x 20")		22	K		
Building Envelope:						
	15 psf Assumed		122	K		
Level 7 Total:			3792	К		

Structural Option Potomac, MD

Consultant: Professor Parfitt 10/05/2009

Table 21: Levels 3-6 Self Weight					
Slab Weight:	7" Thick Slab		2299	K	
PT Beam Weight:			879	K	
Primary Column Weight:	(32) 24" x 24" Columns		240	K	
Superimposed Dead:	5 psf		131	K	
Building Core:					
	(12) 12" x 24" Columns		45	K	
	Core Beams (12" x 30")		17	K	
	Core Beams (12" x 24")		24	K	
	Core Beams (12" x 20")		22	K	
Building Envelope:					
	15 psf Assumed		120	K	
Level 3-6 Total:			3777	K - Per Floor	

Table 22: Level 2 Self Weight					
Slab Weight:	7" Thick Slab		2299	K	
PT Beam Weight:			879	K	
Primary Column Weight:	(32) 24" x 24" Columns		293	K	
Superimposed Dead:	5 psf		131	K	
Building Core:					
	(12) 12" x 24" Columns		55	K	
	Core Beams (12" x 30")		17	K	
	Core Beams (12" x 24")		24	K	
	Core Beams (12" x 20")		22	K	
Building Envelope:					
	15 psf Assumed		120	K	
Level 2 Total:			3840	К	

Structural Option Potomac, MD

Consultant: Professor Parfitt 10/05/2009

Table 23: Plaza/Ground Level Self Weight						
Slab Weight:	12" Thick Slab		16348	К		
Columns Above:	(32) 24" x 24"		173	K		
Columns Below:						
	(16) 12" x 24"		26	K		
	(163) 18" x 36"		605	K		
	(19) 24" x 24"		63	K		
	(4) 24" x 30"		17	K		
	(5) 24" x 42"		29	K		
	(4) 28" x 45"		29	K		
	(4) 30" x 72"		50	K		
	(1) 39" x 36"		8	K		
Drop Panels:	(225) 10' x 10' x 5.5"		1547	K		
Building Core:						
	Core Beams (12" x 30")		17	K		
	Core Beams (12" x 24")		24	K		
	Core Beams (12" x 20")		22	K		
Building Envelope:						
	15 psf Assumed		86	K		
Plaza/Ground Total:			19043	К		

Structural Option Potomac, MD

Consultant: Professor Parfitt 10/05/2009

Table	Table 24: P1 Parking Level Self Weight					
Slab Weight:	8" Thick Slab		10899	K		
Columns:						
	(16) 12" x 24"		50	K		
	(163) 18" x 36"		1155	K		
	(19) 24" x 24"		120	K		
	(4) 24" x 30"		32	K		
	(5) 24" x 42"		55	K		
	(4) 28" x 45"		55	K		
	(4) 30" x 72"		95	K		
	(1) 39" x 36"		15	K		
Drop Panels:	(225) 10' x 10' x 5.5"		1547	K		
Building Core:						
	Core Beams (12" x 30")		17	K		
	Core Beams (12" x 24")		24	К		
	Core Beams (12" x 20")		22	K		
Level P1 Total:			14085	К		

Table 25: P2 Parking Level Self Weight					
Columns:					
	(16) 12" x 24"		24	K	
	(163) 18" x 36"		550	K	
	(19) 24" x 24"		57	K	
	(4) 24" x 30"		15	K	
	(5) 24" x 42"		26	K	
	(4) 28" x 45"		26	K	
	(4) 30" x 72"		45	K	
	(1) 39" x 36"		7	K	
Level P2 Total:			751	К	

Park Potomac Office Building "E"

Structural Option Potomac, MD

Consultant: Professor Parfitt 10/05/2009

Total Building Weight (N-S):	61037	К
---------------------------------------	-------	---

Total	
Building	27330 K
Weight	2/33U K
(E-W):	

	Table 2	6: Base Shears	
	Effective Seismic Weight	Seismic Response Coefficient	Base Shear (K)
N-S	W = 61037 K	Cs = 0.0246	1502
E-W	W = 27330 K	Cs = 0.0210	574

Structural Option

Potomac, MD

Consultant: Professor Parfitt

10/05/2009

		Table	e 27: Seis	smic Cal	culations	s			
Level	Story Weight (K)	N-S Height (ft)	E-W Height (ft)	N-S Forces (K) Fx	E-W Forces (K) Fx	N-S Story Shear Vx	E-W Story Shear Vx	N-S Moments (ft-k) Mx	E-W Moments (ft-k) Mx
Penthouse Roof	557	130.5	109.5	23	15	0	0	3063	1674
Main Roof	3858	114.5	93.5	289	153	23	15	33114	14337
7th Floor	3792	101.5	80.5	239	123	313	169	24231	9939
6th Floor	3777	89	68	198	99	551	292	17600	6711
5th Floor	3777	76.5	55.5	160	76	749	391	12254	4209
4th Floor	3777	64	43	125	54	909	467	7998	2342
3rd Floor	3777	51.5	30.5	92	35	1034	521	4756	1064
2nd Floor	3840	39	18	64	18	1127	556	2502	324
Plaza/First Floor	19043	21	0	252	0	1191	574	5287	0
P1 Level	14085	10	-	59	-	1443	-	589	-
P2 Level/Foundation	751	0	-	0	-	1502	-	0	-
Total:	61037	130.5	109.5	1502	574			111395	40600

Σ w _i h _i ^k N-S	374472090
Σ w _i h _i ^k E-W	60765273

Structural Option Potomac, MD

Consultant: Professor Parfitt 10/05/2009

Technical Assignment #1

Appendix C: Spot Checks

Structural Option

Potomac, MD

Consultant: Professor Parfitt 10/05/2009

	KYLE WAGNER	TECH 1.	SPOT CHECKS	1
	CHECK COLOMI	7 HS		
CAMPAD	24"	f'c =	24" (8)#8 ,#3TIES@16" :400 ps: :60 ks: CK AT LEVEL 6-7 =8(0.79 in") = 6.32"	o.c.
		= 60 = 6.00207 29.000	2 - (\forall \)	
	Po = 2310		85 (4) (24x24)-6.52] + 6.32 (60	9)
	C = 0,003 +	$\frac{3}{2}$ $\frac{3}$		
	0.003	3 (21.625) +0.00207 = 0.85 (12.796") =		
	Ec=Eo Esi Esz	E53 STRAINS	Es: = 0.003 (10.88-2.375) = 6.00235 \(\xi \) = 6.00235 \(\xi \) 6.00235 \(\xi \)	>l

Potomac, MD

Structural Option

Consultant: Professor Parfitt 10/05/2009

	KYLE WAGNER TECH 1. SPOT CHECKS 2
	Esz = 0.003 (10.88-12) = -0.000309 10.88 Fsz = -0.000309 (29.000) = -3.96 Ks;
	E53 = 6.003 (10.88-21.625) = -0.00296
TAPAD	-0.60296 (29000) = -85.92 KS: → f53=-fy=-60 KS
	$P_b = 6.85(4)(24)(6.85)(10.88) + 3(60) + 2(-8.96) + 3(-60)$ $P_b = 736.7 \text{ K}$
	Mb = 6.85 (4)(24)(0.85)(1088)(12 - 6.85(12.796))
	+3(60)(12-2.375) + 2(8.96)(12-12) + 3(-60)(12-21.625)
	Mb = 3416" = 701"
	PURE BENDING
	ASSOME ESI DOES NOT YIELD, ESZ AND ESS YIELD
	for = 0.003 (c-2.375) 29,000
	fsz =-60 Ksi
	fs3 = -60 KSi
	5 F=0 = 0.85 (4)(24)(0.85)C + 3fs, +2fsz +3fs3
	C=3.284"
	VERIFY: ES, = (0.003) (3.284-2.375) = 6.000830 60.00207
	fs1 = 24.08 KSi

Structural Option

Potomac, MD

Consultant: Professor Parfitt

10/05/2009

	KYLE WAGNER TECH ! SPOT CHECKS 3
	E 5 2 = 6.003 (3.284-12) = -6.00796 70.00207
	1. Fsz = -60 KS: Fs3 = -60 KSi
	Mo = 0.85(4)(0.85)(3.284)(12 - 0.35(3.284))
IPAD	+ 3(24.08) + 2(-60)(12-12) + 3(-60(12-21.625)
	Mo = 4220" Mo = 351.7 1K
	PORE TENSION
	To = 2 Asi . Fix = 6.32 in260 Ksi = -379.2 K
	POINT BETWEEN PS AND BALANCED STRAIN
	PIEK C= 24"
	Esi = 0.003 (24-2.375) = 0.0027 > Ey → Fsi=60 ks;
	Esz = 0.003 (24-12) = 0.0015 CEy -Fsz=43.5 Ksi
	Esz = 0.003 (24-21.625) = 6.000297 6 Ey = 953 = 8.61 Ksi
	Pn = 0.85(4)(24)(0.85)(24) + 3(66) + 2(43.5) + 3(8.61)
	Pa= 1957.5K
	Mn = 0.85(4)(24)(0.85)(24)(12 - 0.85(24)) + 3(60)(12-2.375)
	+2(43.5)(12-12) + 3(8.61)(12-21.625)
	Mn= 4905.411K = 408.81K


Structural Option Potomac, MD

Consultant: Professor Parfitt 10/05/2009

	KKLE WAGNER TECH! SPOT CHECKS	4
	AXIAL LOAD	
	TRIB AREA = 1007.9 SF	
	PU = 696 K HERE (FROM COLUMN SCHEPULE)	
	→ GRAVITY DALY CODS, DERED HEBE	
CAMPAD	Pn=0.65(2316.1)=1505 > Po=690 € OKAY -	

Structural Option Potomac, MD

Consultant: Professor Parfitt 10/05/2009



Structural Option Potomac, MD

Consultant: Professor Parfitt 10/05/2009

Krei	E WAGDER TECH 1.	SPOT CHECKS	2
Fe	AME B: EFRAMEA	+79.9 -148 -148	
FR	M=0.65(70)=45.5 M=0.35(70)=24.5	+24.5 -45.5	
	OLOMN STRIP WIDTH = SMALLER O		
C	HELL SLAB THICKNESS		
	TBL 9.52 - INTOROR PAN	DEL W/ DEOPS	
	1 = (28 - 18/12) 36	(IZ) _ 3.83" > 8"	
	ACTUAL SLAB t = 8"	DEFLECTION NEEDS CHECKED	
	WILL NOT CHECK FOR	- PORPOSES OF THIS ANAUCS IS	>
	$\frac{9z}{2} = \frac{23!}{13!} = 2.154$	-22.77 18/6+	
Fe	AME A AND FRAME B		
	MIDDLE STRIP = 6.5	E29 " M5 = 6.5"	
	m+ = 79.9 Ft-1 12.29 14/F+		
	m=-148+- =-22.77 14/F+	. 22.7718/8+	
FR	AME C AND FRAME D	1.1414/5+	
	M+ = 24.5 FH-K 1.14 14/F+ -714/	77.70	
	M = -45.5 = -7 14/2+	C5=325' M5 C5=3.25'	

Structural Option Potomac, MD

Consultant: Professor Parfitt 10/05/2009

KYLE WAGNER	TECH!	SPOT CHECKS	3
REINFORCEMEN	OT REQUIRED		
FRAME A A	oo B		
CS :	$A_{5} = \frac{22.77}{4(8-1.5-0.87\%_{2})} = 1$	5.939 in 7/F+	
	#7 - 0.66 m2		
	#7 @ 18" REQ		
ms:	As = 12.29 4(8-1.5-0.625/2)	0.497 17/ ++	
	#5 - 0.31 11/64		
	#5 @ 20" REQ		
FRAME C N	D ac		
CS:	As = -714/++ 4(8-15-0-625/2)	E 6.283 107/FF	
	#5@12"		
ms .	AS = 1.1418/e+	IN ² /_	
1113	4(8-15-0425/2)		
	USE MINIMUM		

Park Potomac Off	ice Building "E"
------------------	------------------

Structural Option Potomac, MD

Consultant: Professor Parfitt 10/05/2009

Technical Assignment #1

Appendix D: Photos

Consultant: Professor Parfitt 10/05/2009



Figure 11: Front Courtyard



Figure 12: Slab End Cantilever Provides Seamless Glass Corners

Consultant: Professor Parfitt 10/05/2009



Figure 13: Shallow, Wide PT Beams



Figure 14: East View