

Light Loss Factor Calculator

Other Factors	Results
Lamp Burnout Factor	LLD 0.90
Room Surface Dirt Depreciation Factor	LDD 0.93
Luminaire Ambient Temperature Factor	Ballast 0.88
Heat Extraction Thermal Factor	Other 0.95
Voltage-to-Luminaire Factor	
Ballast-Lamp Photometric Factor	
Equipment Operating Factor	
Lamp Position Factor	
F1	
Total LLF 0.70	

Cancel Back Next OK

Light Loss Factor Calculator

Other Factors	Results
Lamp Burnout Factor	LLD 0.90
Room Surface Dirt Depreciation Factor	LDD 0.93
Luminaire Ambient Temperature Factor	Ballast 0.88
Heat Extraction Thermal Factor	Other 0.95
Voltage-to-Luminaire Factor	
Ballast-Lamp Photometric Factor	
Equipment Operating Factor	
Lamp Position Factor	
F5	
Total LLF 0.70	

Cancel Back Next OK

Light Loss Factor Calculator

Other Factors	Results
Lamp Burnout Factor	LLD 0.97
Room Surface Dirt Depreciation Factor	LDD 1.00
Luminaire Ambient Temperature Factor	Ballast 0.88
Heat Extraction Thermal Factor	Other 0.95
Voltage-to-Luminaire Factor	
Ballast-Lamp Photometric Factor	
Equipment Operating Factor	
Lamp Position Factor	
F2	
Total LLF 0.81	

Cancel Back Next OK

Light Loss Factor Calculator

Other Factors	Results
Lamp Burnout Factor	LLD 0.97
Room Surface Dirt Depreciation Factor	LDD 0.93
Luminaire Ambient Temperature Factor	Ballast 0.88
Heat Extraction Thermal Factor	Other 0.95
Voltage-to-Luminaire Factor	
Ballast-Lamp Photometric Factor	
Equipment Operating Factor	
Lamp Position Factor	
F6	
Total LLF 0.75	

Cancel Back Next OK

Light Loss Factor Calculator

Other Factors	Results
Lamp Burnout Factor	LLD 0.97
Room Surface Dirt Depreciation Factor	LDD 1.00
Luminaire Ambient Temperature Factor	Ballast 0.88
Heat Extraction Thermal Factor	Other 0.95
Voltage-to-Luminaire Factor	
Ballast-Lamp Photometric Factor	
Equipment Operating Factor	
Lamp Position Factor	
F3	
Total LLF 0.81	

Cancel Back Next **OK**

Light Loss Factor Calculator

Other Factors	Results
Lamp Burnout Factor	LLD 0.97
Room Surface Dirt Depreciation Factor	LDD 0.93
Luminaire Ambient Temperature Factor	Ballast 0.88
Heat Extraction Thermal Factor	Other 0.95
Voltage-to-Luminaire Factor	
Ballast-Lamp Photometric Factor	
Equipment Operating Factor	
Lamp Position Factor	
F7	
Total LLF 0.75	

Cancel Back Next OK

Light Loss Factor Calculator

Other Factors	Results
Lamp Burnout Factor	LLD 0.97
Room Surface Dirt Depreciation Factor	LDD 1.00
Luminaire Ambient Temperature Factor	Ballast 0.88
Heat Extraction Thermal Factor	Other 0.95
Voltage-to-Luminaire Factor	
Ballast-Lamp Photometric Factor	
Equipment Operating Factor	
Lamp Position Factor	
F4	
Total LLF 0.81	

Cancel Back Next OK

Light Loss Factor Calculator

Other Factors	Results
Lamp Burnout Factor	LLD 0.97
Room Surface Dirt Depreciation Factor	LDD 0.93
Luminaire Ambient Temperature Factor	Ballast 0.88
Heat Extraction Thermal Factor	Other 0.95
Voltage-to-Luminaire Factor	
Ballast-Lamp Photometric Factor	
Equipment Operating Factor	
Lamp Position Factor	
F8	
Total LLF 0.75	

Cancel Back Next OK

Light Loss Factor Calculator

Other Factors	Results
Lamp Burnout Factor	LLD 0.97
Room Surface Dirt Depreciation Factor	LDD 1.00
Luminaire Ambient Temperature Factor	Ballast 0.88
Heat Extraction Thermal Factor	Other 0.95
Voltage-to-Luminaire Factor	
Ballast-Lamp Photometric Factor	
Equipment Operating Factor	
Lamp Position Factor	
	F9
	Total LLF 0.81

Cancel Back Next OK

Light Loss Factor Calculator

Other Factors	Results
Lamp Burnout Factor	LLD 0.74
Room Surface Dirt Depreciation Factor	LDD 1.00
Luminaire Ambient Temperature Factor	Ballast 0.88
Heat Extraction Thermal Factor	Other 0.95
Voltage-to-Luminaire Factor	
Ballast-Lamp Photometric Factor	
Equipment Operating Factor	
Lamp Position Factor	
	F10
	Total LLF 0.62

Cancel Back Next OK

Light Loss Factor Calculator

Other Factors	Results
Lamp Burnout Factor	LLD 0.74
Room Surface Dirt Depreciation Factor	LDD 1.00
Luminaire Ambient Temperature Factor	Ballast 0.88
Heat Extraction Thermal Factor	Other 0.95
Voltage-to-Luminaire Factor	
Ballast-Lamp Photometric Factor	
Equipment Operating Factor	
Lamp Position Factor	
	F11
	Total LLF 0.62

Cancel Back Next OK

Light Loss Factor Calculator

Other Factors	Results
Lamp Burnout Factor	LLD 0.74
Room Surface Dirt Depreciation Factor	LDD 1.00
Luminaire Ambient Temperature Factor	Ballast 0.88
Heat Extraction Thermal Factor	Other 0.95
Voltage-to-Luminaire Factor	
Ballast-Lamp Photometric Factor	
Equipment Operating Factor	
Lamp Position Factor	
	F12
	Total LLF 0.62

Cancel Back Next OK