

Photos Taken for Week Ended 10-10-08

Contents

North and East Façade from NE Corner..... 2

East Façade 3

South Façade (East Half) from Access Road..... 4

South Façade (West Half) from Access Road 5

West Façade from Parking Lot 6

North and West Façade from NW Corner 7

1st Floor Lobby – Stair C Poured 8

3rd Floor – Hanging Drywall..... 9

9th Floor – Floor Leveling (East Half)..... 10

11th Floor – Terrace Wall 11

15th Floor – Demising Wall..... 12

19th Floor – Terrace Wall (North D – E Line) 13

20th Floor – Storefront (NW Corner) 14

North and East Façade from NE Corner



East Façade



South Façade (East Half) from Access Road



South Façade (West Half) from Access Road



West Façade from Parking Lot



North and West Façade from NW Corner



1st Floor Lobby – Stair C Poured



3rd Floor – Hanging Drywall



9th Floor – Floor Leveling (East Half)



11th Floor – Terrace Wall



15th Floor – Demising Wall



19th Floor – Terrace Wall (North D – E Line)



20th Floor – Storefront (NW Corner)

