

Photos Taken for Week Ended 12-12-08

Contents

North and East Façade from NE Corner 2

East Façade 3

South Façade (East Half) from Access Road..... 4

South Façade (West Half) from Access Road..... 5

West Façade from Parking Lot..... 6

North and West Façade from NW Corner..... 7

1st Floor Lobby (From Stair C)..... 8

Unit 304 – Kitchen Area 9

4th Floor – Prime Coat 10

16th Floor – Demising Wall (C-Column 6-Line) 11

17th Floor – Stocking..... 12

20th Floor – NW Corner 13

North and East Façade from NE Corner



East Façade



South Façade (East Half) from Access Road



South Façade (West Half) from Access Road



West Façade from Parking Lot



North and West Façade from NW Corner



1st Floor Lobby (From Stair C)



Unit 304 – Kitchen Area



4th Floor – Prime Coat



16th Floor – Demising Wall (C-Column 6-Line)



17th Floor – Stocking



20th Floor – NW Corner

